



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 16	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 16 (4th of 4 here) (same as felled tree) check map	434108.91	385585.78	Tilia americana 'Redmond'	434109.05	385585.91
o/s 16	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 16 (just past r-about, 1st of 4 here, same as felled tree)	434117.96	385550.03	Tilia americana 'Redmond'	434117.96	385549.98
o/s hotel gates (opp 42, at gated entrance to hotel)	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit at side of gated entrance to hotel, opp 42 (same as felled tree)	434042.46	385421.98	Tilia americana 'Redmond'	434042.76	385421.88
o/s 16	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 16 (3rd of 4 here) (same as felled tree) check map	434112.13	385571.8	Tilia americana 'Redmond'	434112.31	385571.58
o/s 42	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 40 (OPPOSITE driveway for Kenwood Hall) (same as felled tree)	434019.57	385418.35	Tilia americana 'Redmond'	434027.72	385422.99
o/s 11	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit centrally o/s 11 (same as felled tree)	434121.54	385574.67	Tilia americana 'Redmond'	434121.54	385574.9
o/s 3	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 3 (OPPOSITE 4) (same as felled tree)	434117.72	385665.86	Tilia americana 'Redmond'	434117.42	385665.76
o/s 12	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 12 (same as felled tree) check map	434107.13	385597.47	Tilia americana 'Redmond'	434107.32	385597.63
o/s 8 (OPPOSITE 7)	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 8 (OPPOSITE 7) (same as felled tree) check map	434106.46	385619.85	Tilia americana 'Redmond'	434106.42	385619.8

Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 16	KENWOOD ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 16 (2nd of 4 here) (same as felled tree) check map	434116.12	385560.02	Tilia americana 'Redmond'	434116	385560.51